

The Highest Quality Weld Repairs
Alexsons
 Certified Aircraft Weld Repairs Inc.

Seneca College (CYPQ) APP# A 1.0 334-92
 Qty 1
 Desc EXHAUST
 SN/Bat#
 Exp
 P/N 35-950005-39
 Model
 Loc N2
 TTSO
 Printed on Apr 6, 2017
 8968

45121 5 Side Road
 East Garafraxa, ON
 L9W 7E6
 Telephone & Fax: (519) 942-6235

SERVICE DESCRIPTION AND CERTIFICATION

MIL STD 2219

Customer Seneca College Purchase Order 120160 Date Received 3-17-17 Work Order No. 32-227

Item	Part Description	Part Number	Manufacturer	Model	Quantity
1	EXHAUST collector	35-950005-39	Beech	F-33	1
2					
3		AK C-655W			

Item	Repaired/Replaced/ overhauled/ Modified	General Welding	Crack(s)	Overlap Patch	Splice	Flange	Beaded/Flared End(s)	Bell/Ball/Silp Joint(s)	Muffler Body	Tail Pipe	End Cap	Heat Baffle	Inlet Tube	Shroud Ring	Heat Shroud Support
1	Repaired				✓	✓									
2															
3															

Report/Specifications Weld Repaired AS PER ALEXSONS APP R.O.C # A-RA96-003
SECTION 4.2.2 (C) 4.2.3 (E)

Item	Welding Method	Current	Approval No./Issue Date	Preheat	Post Heat	Material/Receiving No.	Range	Filler Rod/Receiving No.
1	TIG	DC	0921-13 10-18-13			30455 95306 049	30855 952-104	
2						30455 95257 0250		
3								

Final Inspection Detail

Item	Pressure Test	Non-Destructive Testing	Other
1	✓		S/B
2			
3			

Machine No. 1

Welder (S2)

CERTIFICATE OF CONFORMANCE:

I hereby certify that the items listed above have been inspected and tested and conform to all specification and requirements as detailed in the contract/purchase order. This document does not constitute a maintenance release according to the requirements of CAR 571.

On behalf of Alexsons Certified Aircraft Weld Repairs Inc.

Approved Inspector Signature & Stamp

Date 4-4-17