

# Air Services Branch

Transportation and  
Government Services



NOMENCLATURE: RM1

MANUFACTURER: KING

P/N 066-3060-00 S/N 2700 MODEL KN1582

T.S.N. \_\_\_\_\_ T.S.O. \_\_\_\_\_ T.B.O. \_\_\_\_\_

PREVIOUS CERTIFICATION A/C RNE WO# \_\_\_\_\_ TASK# \_\_\_\_\_

INSP. ☐ SHOP CHECK ☐ NEW ☐

REPAIR ☒ OVERHAUL ☐ BY KYLE TUSTIN P/O.W/O# C00049-0039

The maintenance described has been performed in accordance with the  
applicable standards of airworthiness.

JUL 24/13 KYLE TUSTIN  
Date Name of Authorized Inspector

2-76  
DOT Approval No.

436194 KL  
Lic. No/Stamp

MAINTENANCE RELEASE

## Province of Manitoba-Air Services Branch

UNSCHEDULED

## Cost Center Task Card

C00049 - 0039

Customer: Province of Manitoba-Air Services Branch

Report Date: 07/24/2013 @ 13:53:14

Department: 000032 - AVIONICS SHOP

Serial No.: n/a

TTSN: n/a

Completed @: \_\_\_\_\_

TCSN: n/a

Vol: \_\_\_\_\_ Page: \_\_\_\_\_

Issued Date: 10/22/2012

ATA: \_\_\_\_\_

Issued by: MAINT

**Due on**

BENDIX/KING RMI KNI-582, P/N 066-3060-00, S/N 2700

OCT 22, 2012 NEEDS 28 VOLT LIGHTING REPAIRED. // PREV. WO# C12-0062 MAY 03, 2005

REMOVED FROM C-GRNE OCT. 28, 2008 TASK 080494-0030 REPAIR ORDER M7383

**Corrective Action**

Lamps Replaced and lighting tested Serviceable as per MM KNI582 pn 006-0193-02

Work Done By: KYLE TUSTIN Licence: 436194 Date: JULY 24/13.**Parts Installed**

| Qty | Part Number | Description | SN ON | SN OFF | Batch # |
|-----|-------------|-------------|-------|--------|---------|
|     |             |             |       |        |         |
|     |             |             |       |        |         |
|     |             |             |       |        |         |
|     |             |             |       |        |         |

Does this require an independent signature? Yes ☐ No ☒*"I have conducted an inspection for conformance to the type of flight/power plant controls that were affected by the work accomplished."*

Ind. Signature: \_\_\_\_\_ Licence: \_\_\_\_\_ Date: \_\_\_\_\_

*"The maintenance described above has been performed in accordance with the applicable standards of airworthiness." AMO 2-76*Signature: [Signature] Insp. Stamp/Licence: 436194 KT Date: JUL 24/13.

| Personnel | Date | Remarks | Time On | Time Off | Total Hours |
|-----------|------|---------|---------|----------|-------------|
|           |      |         |         |          |             |
|           |      |         |         |          |             |
|           |      |         |         |          |             |
|           |      |         |         |          |             |
|           |      |         |         |          |             |

Note: Attach 'all' supporting documentation including serviceable tags, certification statements, requisitions, etc.

\_\_\_\_\_ Data Entered

\_\_\_\_\_ MCN Updated

**C00049 - 0039**  
**UNSCHEDULED**