


1. Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE			3. Form tracking No. N/A	
4. Approved organization name and address SENECA COLLEGE OF APPLIED ARTS AND TECHNOLOGY 1750 FINCH AVE E. NORTH YORK ONTARIO M2J 2X5					5. Work order/contract/invoice N/A	
6. Item	7. Description	8. Part No.		9. Qty.	10. Serial/batch No.	11. Status/work
1	Bonanza Main Wheel	40-83B	NA	1	N/A	Repaired
12. Remarks Bonanza Main Wheel assembled with the following parts: New Tire P/N 072-313-0 Tracking # 9025, New brake Disc P/N 164-02505 T/N 9028 and New bolts Qty 3, P/N AN5-36A B/N 661 Check Tire Pressure on Installation						
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non approved design data specified in block 13.			14a. ☒ CAR 571.10 Maintenance release. ☐ Other regulations specified in block 12. Certifies that, except where otherwise specified in block 13, the work identified in block 12 and described in block 13 was performed in accordance with CAR 571.			
14b. Authorized signature N/A		14c. Certificate/Approval ref. No. N/A		14b. Authorized signature 		14c. Certificate/Approval ref. No. AMO 334-92
14d. Name N/A		14e. Date (dd/mm/yyyy) N/A		14d. Name Jeffery Anderson M825814		14e. Date 11 January/2019

1. This document does not constitute authority to install the part
2. Where the installer works in accordance with the national regulations of an airworthiness authority other than the authority specified in block 1, the installer must ensure that his/her airworthiness authority accepts products or maintenance from the airworthiness authority specified in block 1.
3. Statements 13a and 14a do not constitute installation certification. In all cases the technical records for the aircraft must contain an installation certification, issued in accordance with the applicable national regulations before the aircraft may be flown.